



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 18 August 2010
Subject: Bydgoszcz, Poland
Szwederowo (EPBY)
Multiple Approach Procedures
Cycle 1009

Approach Procedures Unusable

Jeppesen NavData for cycle 1009, effective 26 August 2010, contains incorrect approach procedure information for Szwederowo Airport; Bydgoszcz, Poland (EPBY).

THEREFORE, DO NOT USE THE APPROACH PROCEDURES LISTED BELOW IN CYCLE 1009 NAVDATA.

ILS DME Z Rwy 26 [I26-Z]
NDB Rwy 26 [N26]

Revised coding will appear in Jeppesen NavData for cycle 1010, effective 23 September 2010. Until then an entry will appear in the NavData Change Notices beginning 20 AUG 2010, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Eastern%20Europe>) .

Please refer to the Bydgoszcz, Poland (EPBY) 11-1, 16-1 and 16-2 charts dated 20 AUG 10 (effective 26 August 2010) for valid information.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.