



JEPPESEN[®]

NavData[®] Alert

!! URGENT !!

Date: 6 August 2010

Subject: Indianapolis, Indiana
Indianapolis Intl (KIND)
MEARZ ONE DEPARTURE [MEARZ1]
Cycle 1008

Missing Waypoints on Departure Enroute Transitions

Jeppesen NavData for cycle1008, effective 29 July 2010, contains incorrect Enroute Transition routing for the MEARZ One Departure [MEARZ1] at Indianapolis Intl; Indiana (KIND).

Enroute Transition	Waypoint Missing	Correct Routing
BOILER [BVT]	SACHS N40-08-39 W086-30-42	MEARZ – SACHS - BVT
KOKOMO [OKK]	SHAWW N40-08-59 W086-14-11	MEARZ – SHAWW - OKK
MARION [MZZ]	BRATN N40-08-14 W086-07-45	MEARZ – BRATN - MZZ

THEREFORE, EXERCISE CAUTION WHEN USING THE MEARZ ONE DEPARTURE [MEARZ1] IN CYCLE 1008 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1009, effective 26 August 2010. Until then an entry will appear in the NavData Change Notices beginning 13 AUG 10, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/aviation-alerts.jsp?region=United%20States>). Please refer to the Indianapolis, IND (KIND) 10-3B chart dated 23 JUL 10 (effective 29 July 2010) for valid information.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

KIND 1008